
JMH Retrofit LCD Signs Photo Gallery

March 15, 2019 – March 27, 2019

Jackson Memorial Hospital University of Miami Miami, Florida



LCD Signs Site One Door opening direction Jackson Memorial Hospital, Miami, Florida

















LCD Signs Site Two















LCD Signs Site Three Door opening direction

North Site-3 S/N #14

East Site-3 S/N#15

West Site-3 S/N #13

South Site-3 S/N#16














LCD Signs Site Four Door opening direction







Door Hinge Operation



































Baseplate Cutting and Hinge Colliding are Cutting











LED Side Signs Retrofit and Wiring

Site-One :East(S/N#11) Extended LED power wires
When the door open, wires disconnected. Solve with extended wiring. Testing success.







Unidentified damaged one glass (Wrapping not damaged)

1: Site-Four S/N #5 Logo cover glass crack (Replace glass)

* Deliver one new glass - Maintenance





Site-Four Kiosk 4: Side bar cutting, Base cutting, Caster, Painting







Site-Two Kiosk 2: Welding work and Caster Installation Work





Kiosks after finishing retrofit caster: Kiosk 1 and Kiosk 2







Kiosk 1







Kiosk 2

Kiosks after finishing retrofit caster: Kiosk 3 and Kiosk 4





